


[CLICK HERE TO SIGN UP FOR BUILDINGS NEWS](#)
NYC Department of Buildings
Overview for Complaint #:1730062 = RESOLVED

Complaint at: **235 EAST 42 STREET** BIN: **1037552** Borough: **MANHATTAN** ZIP: **10017**
 Re: SITE SAFETY MANAGER REPORTED THAT STEEL BEAM WAS COMPROMISE ON THE 21ST FLOOR,NO INJURY

Category Code: 91 SITE CONDITIONS ENDANGERING WORKERS

Special District: MID - MIDTOWN
 TA - TRANSIT LAND USE

Assigned To: CONSTRUCTION SAFETY ENFORCMENT **Priority:** A

Received: 07/07/2026 **Block:** 1316 **Lot:** 23 **Community Board:** 106
Owner: X X

Last Inspection: 07/08/2026 - - BY BADGE # 2985

Disposition: 07/08/2026 - L1 - PARTIAL STOP WORK ORDER

Comments: At time of inspection in response to an incident where 2 steel column buckled on 21 floor and caused structural damage on multiple floors. Stop all construction activities on entire jobsite except for emergency work under full time PE and CS supervision. CSE AUDIT

Prev DOB Violation #: VIO26-50594

Complaint Disposition History

#	Disposition		Disposition	Inspection By	Date
	Date	Code			
2	07/08/2026	L1	PARTIAL STOP WORK ORDER At time of inspection in response to an incident where 2 steel column buckled on 21 floor and caused structural damage on multiple floors. Stop all construction activities on entire jobsite except for emergency work under full time PE and CS supervision. CSE AUDIT	2985	07/08/2026
1	07/08/2026	A3	FULL STOP WORK ORDER SERVED IN RESPONSE TO INCIDENT WHERE 2 STEEL COLUMN BUCKED ON 21 FL R. AND CAUSE STRUCTUAL DAMAGE MULT FLOORS	3149	07/07/2026

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.